



The working size depends on the machine size and it's got the following values:

1. Small machine

	A max	A min	B max	B min	C min	D min	F min
No lock	700 mm	70 mm	600 mm	110 mm	6 mm	70 mm	51 mm
Lock	700 mm	160 mm	570 mm	180 mm	9 mm	90 mm	85 mm

2. Big machine

	A max	A min	B max	B min	C min	D min	F min
No lock	700 mm	70 mm	800 mm	110 mm	8 mm	70 mm	51 mm
Lock	700 mm	160 mm	770 mm	180 mm	9 mm	90 mm	85 mm